
GDF60-18Z/4.5 220 V Outline diagram



Special attention: thread locking adhesive shall be applied or the spring washer shall be added to prevent the looseness during the installation of the fastening screw!