Output Input **Ø**100 **4−ø**6. 5 4-M5X12 \$73G7 \$70h7 **ø**25 9.69 Ø12.7F7 ø12.7h6 47.01 69.6 11.7 97.5 51 86X86 85X85 Four screw holes to tight