




24VDC  
Power  
Supply

110V AC



V-

V+

J4

J5




KL-600-48

48V/12.5A  
Power Supply

L N G V+ V-

110V AC



ECAT  
OUT

ECAT  
IN

15+

13+

11

C+

O1

A- A+

B- B+

GND

15-


13-

12

C-

O2

+VDC



ECAT  
OUT

ECAT  
IN

15+

13+

11

C+

O1

A- A+

B- B+

GND

15-


13-

12

C-

O2

+VDC



ECAT  
OUT

ECAT  
IN

15+

13+

11

C+

O1

A- A+

B- B+

GND

15-


13-

12


C-

O2


+VDC



M



M



M

**AUTOMATION  
TECHNOLOGY**  
Motion Control Parts and CNC Equipment.